



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah


DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program December 15, 2009

Reviewed: 

Mine Name: Velvet	Permit Number: M/037/0040
Operator Name: Uranium One	Inspection Date: October 7, 2009
Inspector(s): T Munson	Time: 1 PM
Other Participants: Larry Trimble	Mine Status: Ins ACTIVE

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$118,853.00

Permit Fees: current


Purpose of Inspection: Annual inspection

Inspection Summary: The Velvet mine remains inactive. There has been no physical development, maintenance, reclamation activities or any new surface disturbances of any kind at this mine in 2009. The mine remains essentially fully reclaimed with a full reclamation bond in place. Uranium One has no immediate plans to move forward with this project and has committed to the Division that no mining will take place until a new Plan of Operations and updated reclamation bond is approved by the Division.

Photos were taken to document site conditions.

Conclusions and Recommendations:

The site be inspected annually.

Inspector's Signature 

Tm:vs

cc: larry.trimble@uranium1.com

ted_mcdougall@blm.gov

File Name and Path





Reclaimed area



Reclaimed area